UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5

IN THE MATTER OF:)
American Electric Power Buckeye Power) NOTICE OF VIOLATION
Cardinal Plant Brilliant, Ohio) EPA-5-00-OH-4))
Proceedings Pursuant to Section 113(a)(1) of the Clean Air Act, 42 U.S.C. § 7413(a)(1))

NOTICE OF VIOLATION

The Administrator of the United States Environmental Protection Agency (U.S. EPA) is issuing this Notice of Violation under Section 113(a)(1) of the Clean Air Act, 42 U.S.C. § 7413(a)(1). U.S. EPA finds that American Electric Power (AEP)/Buckeye Power - Cardinal Plant is violating the Ohio State Implementation Plan (SIP), as follows:

Statutory and Regulatory Background

- 1. On June 27, 1994, U.S. EPA approved visible emission limit OAC 3745-17-07(A) as part of the federally enforceable SIP for Ohio. 59 Fed. Reg. 27464.
- 2. OAC 3745-17-07(A) establishes that visible particulate emissions from any stack shall not exceed twenty per cent opacity, as a six-minute average.

AEP's Cardinal Plant

- 3. AEP/Buckeye Power owns and operates three coal-fired boilers at its Cardinal Plant located at 306 County Road 7E, Brilliant, Ohio.
- 4. These boilers are designated as Unit 1, Unit 2 and Unit 3.
- 5. Emissions from AEP's three coal-fired boilers at its Cardinal Plant are subject to the visible emission limits in the Ohio SIP at OAC 3745-17-07(A).

Violations

6. On August 4, 1999, U.S. EPA documented violations of the applicable opacity limitation based on the following visible emission observations conducted in accordance with EPA Method 9 at the Unit 1 stack. U.S. EPA alleges that these violations are continuing until such time as AEP provides visible emission observations conducted in accordance with EPA Method 9 documentation demonstrating that this source has returned to continuous compliance.

Time	6-minute Average Opacity	Allowable Opacity Limit
4:50pm - 4:55pm	51%	20%
4:56pm - 5:01pm	56%	20%
5:02pm - 5:07pm	51%	20%

7. On August 4, 1999, U.S. EPA documented violations of the applicable opacity limitation based on the following visible emission observations conducted in accordance with EPA Method 9 at the Unit 2 stack. U.S. EPA alleges that these violations are continuing until such time as AEP provides visible emission observations conducted in accordance with EPA Method 9 documentation demonstrating that this source has returned to continuous compliance.

Time	6-minute Average Opacity	Allowable Opacity Limit
5:09pm - 5:14pm	66%	20%
5:15pm - 5:20pm	66%	20%
5:21pm - 5:26pm	68%	20%

Vove by 30, PP19

Margaret M. Guerriero

Acting Director

Air and Radiation Division

CERTIFICATE OF MAILING

I, Shanee Rucker, certify that I sent a Notice of Violation,
No. EPA-5-99-OH-4, by Certified Mail, Return Receipt Requested,
to:

D.I. Pittenger, Plant Manager American Electric Power/Buckeye Power Cardinal Plant P.O. Box B Brilliant, Ohio 43913

I also certify that I sent copies of the Notice of Violation by first class mail to:

D. Michael Miller, Chief Counsel Power and Generation American Electric Power 1 Riverside Plaza Columbus, Ohio 43215

Mark Gray, Manager of Env. Services Division American Electric Power 1 Riverside Plaza Columbus, Ohio 43215

Robert Hodanbosi, Chief Division of Air Pollution Control Ohio Environmental Protection Agency P.O. Box 1049 Columbus, Ohio 43216

Fred Klingelhafer, APC Supervisor Southeast District Office Ohio Environmental Protection Agency 2195 Front Street Logan, Ohio 43138

on the 30 day of November, 1999.

Shanee Rucker, Secretary AECAS, (MI/WI) (312) 886-6086

CERTIFIED MAIL RECEIPT NUMBER: 2199026 456